

Inlet Impactor

Model 3306

Standard replacement parts for Model 3306 Impactor Inlet consist of:

<u>Part Number</u>	<u>Part Description</u>
1602051	HEPA Capsule Filters (need 2)

For pricing information, or to place an order you can 1) send the necessary information to answers@tsi.com or 2) contact your local TSI representative (see contact information below) and speak to one of our customer specialists. Please include your contact information (telephone number and mailing address) with all requests.

TSI Incorporated – 500 Cardigan Road, Shoreview, MN 55126 U.S.A

USA	Tel: +1 800 874 2811	E-mail: particle@tsi.com	Website: www.tsi.com
UK	Tel: +44 149 4 459200	E-mail: tsiuk@tsi.com	Website: www.tsiinc.co.uk
France	Tel: +33 491 95 21 90	E-mail: tsifrance@tsi.com	Website: www.tsiinc.fr
Germany	Tel: +49 241 523030	E-mail: tsigmbh@tsi.com	Website: www.tsiinc.de
India	Tel: +91 80 41132470	E-mail: tsi-india@tsi.com	
China	Tel: +86 10 8260 1595	E-mail: tsibeijing@tsi.com	

Contact your local TSI Distributor or visit our website www.tsi.com for more detailed specifications.



TRUST. SCIENCE. INNOVATION.